

Supplement 12/63

to Spare Parts List Type 3

New parts:

361 501 105	Tube – Rear axle (M 267)
361 501 106	Tube – Rear axle (M 267)
311 501 163	Bearing housing
311 501 164	Bearing housing
361 501 189 A	Bumper stop
361 501 190 A	Bumper stop
311 501 283	Ball bearing
311 501 317	Washer
311 501 325	Bolt, hex. head (see Workshop Bulletin)
311 705 453	Runner
311 705 454	Runner (see Workshop Bulletin)
141 711 621 0F	Knob (change in production)
361 813 351	Water drain flap (to simplify repairs)
311 821 805 A	1 set of mud flaps white
361 821 805 A	1 set of mud flaps white (now available as spare part)
311 827 301 C	Hood hinge
311 827 302 C	Hood hinge
311 827 413 A	Hinge stay
311 827 531 A	Cable – Rear hood
311 827 545	Conduit tube (see Workshop Bulletin)
361 827 553	Operation washer
361 863 895	Sound absorber (now available as spare part)
111 941 143 D	Bush, rubber (change in production)
111 012 255	Screwdriver
311 016 025	Spare wheel hub cap with tools (new parts)
N 10 254 2	Bolt, hex. head
N 10 465 1	Bolt, hex. head
N 11 020 2	Nut, hex.
N 12 038 1	Lock washer (improvement)
L 140	Repair primer
L 142	Spotting putty (requested by costumers)
L 180.5	Polishing paste (now supplied in 0.5 kg tins)

Section 2:

343 821 805 A	1 set of mud flaps white (now available as spare part)
343 827 081 A	Gasket (see Workshop Bulletin)
343 881 161 A	Knob – Seat back adjustment (change in production)

No longer available:

311 501 067	superseded by: 111 501 105/311 501 163/361 501 189 A
361 501 067	superseded by: 111 501 105/311 501 163/361 501 189 A
311 501 068	superseded by: 111 501 105/311 501 164/361 501 190A
361 501 068	superseded by: 111 501 105/311 501 164/361 501 190A
361 813 373 A	superseded by: 361 813 351
311 827 413	superseded by: 311 827 413 A
L 180	superseded by: L 180.5

Section 2:

341 823 525	will not be introduced
343 827 081	superseded by: 343 827 081 A
343 881 161	superseded by: 343 881 161 A

Delete:

311 119 517	superseded by: 311 119 513 A
311 863 371	superseded by: 311 863 021
311 863 372	superseded by: 311/312 863 022
SP 4	superseded by: SP 504
LK 41	superseded by: LKL 41
LK 456	superseded by: LKL 456
LOM 62	superseded by: LKM 62

At the following part delete in text the Engine-No.:

311 119 513 A	Cover plate
---------------	-------------

On page 9-11 delete profile H 078
at Part No. 111 837 219 AR
(see Parts Department Circular)